



Corrigendum

Corrigendum to “Fatigue behaviour of root crack in stiffener-to-deck plate weld at crossbeam of orthotropic bridge decks” [Eng Struct 306 (2024) 117710 1-16]



Weijian Wu ^{a,*}, Milan Veljkovic ^a, Henk Kolstein ^a, Richard Pijpers ^b, Johan Maljaars ^{b,c}

^a Delft University of Technology, Mekelweg 5, Delft, The Netherlands

^b TNO, Molengraaffsingel 8, Delft, The Netherlands

^c Eindhoven University of Technology, Blauwe Zaale 1, Eindhoven, The Netherlands

The authors regret that due to errors in typing, Eq. (2) and the corresponding texts should be replaced by:

$$\Delta\sigma_{\text{nom}} = \frac{\Delta M \times 0.5t_d}{I} \quad (2)$$

where ΔM is the bending moment range and the second moment of area $I = t_d^3/12$, both in unit width.

The results in the paper are not affected by the typing error. The authors would like to apologise for any inconvenience caused.

DOI of original article: <https://doi.org/10.1016/j.engstruct.2024.117710>.

* Corresponding author.

E-mail address: w.wu-1@tudelft.nl (W. Wu).